August 1987 NSRP 0281

SHIP PRODUCTION COMMITTEE
FACILITIES AND ENVIRONMENTAL EFFECTS
SURFACE PREPARATION AND COATINGS
DESIGN/PRODUCTION INTEGRATION
HUMAN RESOURCE INNOVATION
MARINE INDUSTRY STANDARDS
WELDING
INDUSTRIAL ENGINEERING
EDUCATION AND TRAINING

THE NATIONAL SHIPBUILDING RESEARCH PROGRAM

1987 Ship Production Symposium

Paper No. 8: Submarine Tank Repair Using Outfit Planning

U.S. DEPARTMENT OF THE NAVY CARDEROCK DIVISION, NAVAL SURFACE WARFARE CENTER

including suggestions for reducing	completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding an OMB control number.	arters Services, Directorate for Info	rmation Operations and Reports	s, 1215 Jefferson Davis	Highway, Suite 1204, Arlington			
1. REPORT DATE AUG 1987		2. REPORT TYPE N/A		3. DATES COVERED -				
4. TITLE AND SUBTITLE				5a. CONTRACT	NUMBER			
-	building Research P No.8: Submarine T	•		5b. GRANT NUN	/IBER			
Symposium raper	No.6: Submarme 1	ank Kepan Using U	utilt Flaming	5c. PROGRAM E	ELEMENT NUMBER			
6. AUTHOR(S)				5d. PROJECT NU	JMBER			
				5e. TASK NUME	BER			
				5f. WORK UNIT	NUMBER			
Naval Surface War	ZATION NAME(S) AND AE rfare Center CD Con 128 9500 MacArth	de 2230 - Design In	0	8. PERFORMING REPORT NUMB	G ORGANIZATION ER			
9. SPONSORING/MONITO	RING AGENCY NAME(S) A	AND ADDRESS(ES)		10. SPONSOR/M	ONITOR'S ACRONYM(S)			
				11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT			
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release, distributi	on unlimited						
13. SUPPLEMENTARY NO	OTES							
14. ABSTRACT								
15. SUBJECT TERMS								
16. SECURITY CLASSIFIC	CATION OF:		17. LIMITATION OF	18. NUMBER	19a. NAME OF			
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	- ABSTRACT SAR	OF PAGES 13	RESPONSIBLE PERSON			

Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and


Report Documentation Page

Form Approved OMB No. 0704-0188

DISCLAIMER


These reports were prepared as an account of government-sponsored work. Neither the United States, nor the United States Navy, nor any person acting on behalf of the United States Navy (A) makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness or usefulness of the information contained in this report/manual, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or (B) assumes any liabilities with respect to the use of or for damages resulting from the use of any information, apparatus, method, or process disclosed in the report. As used in the above, "Persons acting on behalf of the United States Navy" includes any employee, contractor, or subcontractor to the contractor of the United States Navy to the extent that such employee, contractor, or subcontractor to the contractor prepares, handles, or distributes, or provides access to any information pursuant to his employment or contract or subcontract to the contractor with the United States Navy. ANY POSSIBLE IMPLIED WARRANTIES OF MERCHANTABILITY AND/OR FITNESS FOR PURPOSE ARE SPECIFICALLY DISCLAIMED.

N S R P 1987 SHIP PRODUCTION SYMPOSIUM



AUGUST 26-28, 1987 HYATT REGENCY HOTEL New Orleans, Louisiana

HOSTED BY THE GULF SECTION OF THE SOCIETY OF NAVAL ARCHITECTS AND MARINE ENGINEERS



TO THE PARTY OF TH

THE SOCIETY OF NAVAL ARCHITECTS AND MARINE ENGINEERS 601 Pavonia Avenue, Jersey City, NJ 07306

Paper presented at the NSRP 1987 Ship Production Symposium, Hyatt Regency Hotel, New Orleans, Louisiana, August 26-28, 1987

Submarine Tank Repair Using Outfit Planning No. 8

Charles P. Dunford, Visitor, and Keith D. Blackler, Visitor, Puget Sound Naval Shipyard, Bremerton, WA

ABSTRACT

Outfit Planning and Zone Logic methods have been implemented in the Shipbuilding Industry in response to the need for increased efficiency in the construction of new ships. Efforts have been under way at Puget Sound Naval Shipyard to use Outfit Planning principles to plan and execute ship alterations on operational ships. The next logical step is to use these same principles to plan and execute overhaul and refurbishment work. This paper addresses efforts at Puget Sound Naval Shipyard to apply Outfit Planning principles to the repair of submarine tanks.

A typical submarine has approximately 60 tanks on board that perform a variety of functions such as liquid storage and control of the ship. During the overhaul period most tanks are opened, inspected, and repaired. Traditional methods of sequencing and controlling the repair functions in the tanks have not always been totally effective. Outfit Planning methods offer an alternative approach.

Outfit Planning in submarine tank repairs makes little use of prefabrication and pre-outfitting. A group-oriented approach to planning and executing work is used to bring together the right people to focus on specific phases of the work. Planning and Production personnel work together to implement usually obvious changes to streamline the work. Acting as a unit, the Group has considerable leverage to influence productivity.

The availability of computer data base management and project management software offers the possibility of developing better tools to track work status, predict work sequences, and predict work loads.

Computer Aided Design (CAD) systems are being used to model tank structure and systems to assist in

the preparation of Unit Work Procedures that specify how tank work is to be accomplished. The result is task level work planning in the form of work sequences and work procedures with input from appropriate trades.

Tank repair using Outfit Planning concepts involves the use of these tools to manage and execute tank work.

INTRODUCTION

Puget Sound Naval Shipyard has been involved in using Outfit Planning and Zone Logic principles for several years (1). Initially, these efforts were focused on shipalts which involved the installation of new systems or new equipment and offered opportunities for prefabrication and pre-outfitting. Naval Shipyards also do a great deal of repair and refurbishment work on existing components. A typical submarine overhaul requires approximately 160,000 mandays of effort. About one half of that is repair work. Puget Sound Naval Shipyard is pursuing the use of the same techniques to plan and accomplish repair work.

U.S. Naval Shipyards are traditional functional organizations, i.e., people, information, and work are grouped by ships systems (2). This type of organization is best suited to the production of uniform products. A Naval Shipyard's workload, however, is characterized by a variety of products built in variable quantities. This inconsistency between organization and function results in systemic problems that inhibit productivity. Two problems characteristic of function-oriented shipyards are:

- 1. Poor interdepartmental communication.
- Work packages that are too large to allow control of material, manhours, and schedule (3).

In the area of shipalt work, Outfit Planning concepts have been effective in increasing productivity through the use of ad hoc committees that focus on products within zones in lieu of systems. Since the Shipyard handles repair work much the same as shipalt work, it follows that there is benefit in applying the same Zone Logic. It is the planning methodology that is important. This is where Puget Sound Naval Shipyard is concentrating its efforts.

Historically, the Shipyard has done a good job of completing submarine tank work to support undocking, but frequently only as a result of some significant eleventh hour heroics on the part of the production workers. A typical submarine undocking is preceded by intense tank work activity to meet schedule. Since the Shipyard's performance is judged by its ability to meet undocking dates, one is left wondering if there isn't a better way to manage tank work that provides more positive assurance of schedule adherence. The recurrence of this feeling at the Shipyard management level has resulted in the formation of the Plant of the Plan tion of an Outfit Planning group to improve the tank repair process.

THE OUTFIT PLANNING GROUP

Initiation of an Outfit Planning group was accomplished by the appointment of a Group Chairman from the Planning Department and a Zone Manager from the Production Department. These two individuals organized a core group of representatives from areas of the Shipyard most involved in the tank repair process. The areas represented

- Design
- Planning and Estimating
- Scheduling
- Test Engineering
- Combat Systems
- Pipefitters
- 7. Shipfitters
- 8. Machinists
- Sandblasters and Painters

A period of time was required to orient and educate the group members in the concepts of Zone Logic. At the beginning of the Group's activity, meetings were held twice a week. The Group familiarized itself with Outfit Planning concepts and with the activities of previously established groups while it struggled with the problem of tank repairs. Immediately there were obvious differences between this project and the chiral activities. project and the shipalt projects pre-viously done. Prefabrication and pre-outfitting are basically not involved in tank repairs. Material

requirements are centered around fixing what already exists. The ship cannot as easily be broken into large blocks as is done with shipalt work. Tanks naturally define many small zones that can be treated separately or as groups. Zone boundaries must be defined for piping systems that interface with tanks so that all work relating to tank testing can be

It was clear that this would be a different use of the Outfit Planning concept. However, some tools were still available to the Group. A fundamental part of any Outfit Planning activity is the group-oriented approach which integrates the basic functions of planning and production. A fresh approach to old problems is more likely to develop in an atmo-sphere that encourages group synergy. Unit work procedures were also seen as a tool for executing repair work. A critical step for the Group was the establishment of a clear-cut objective followed by a plan of action and milestones. Having done this, the Group set to work on implementing the plan.

TANK REPAIR WORK - THE PROBLEM

The attention of the Group was initially focused on isolating the problems that result in a lack of complete control of the tank repair process. A search for problem tanks and problem tank evolutions did not expose any obvious areas where intensified efforts would improve productivity. The problem of tank repairs centers more around the multitude of ${\sf tasks}^{f l}$ that need to be done in order to complete the job. In general, tank work involves the following steps:

- Take custody of the tank
- Open tank Clean
- 3.
- Inspect
- 5. Repair
- 6. Preserve
- 7. Close
- Return tank to ship custody

Consider that these nine evolutions are required for most of the approximately 60 tanks on a typical submarine and you have a minimum of 600 tasks to manage. This figure

¹ The word "task," as used in the Outfit Planning context, is defined as an element of work, performed by a single trade or skill that can be accomplished without interruption.

does not include tasks associated with shipalt work nor does it attempt to itemize all of the inspection and repair items that might be involved. The actual number of tasks to be managed is closer to 1500. Authorization to accomplish the work, in the form of job orders, does not identify these individual tasks, but instead gives a generic description of work. Scheduling relates job orders to schedule events that they must support. All task level work list development and scheduling is done at the worker The Shipfitter General Foremen assigns the tank management responsibility to a mechanic who is known as a Tank Coordinator. It is that person's job to coordinate all tank work such that schedule dates are met. Tools and methods are at the option of the Tank Coordinator. In the past, some have used computers to keep lists of things to do, but the primary management tool has been the wall chart. A great deal of dependence is placed on the skills of the individual Tank Coordinator.

Based on the above, the Outfit Planning Group determined that the tank repair problem was a process oriented problem and that better management tools were needed to manage those processes. A second but related problem identified by the Group was the lack of work instructions specifically for tank repair tasks. Certainly not every task needs an instruction for each tank, but there are those that would benefit. Tasks that the Group felt would benefit from more specific instructions are:

- 1. Initial inspections
- 2. Tank testing
- 3. Returning tanks to ship custody

OUTFIT PLANNING TANK REPAIR WORK

Tank Repair Project Management

Having identified a group of problems related to a lack of tools to manage tank work, the Group set about providing some tools. The first priority was to plan and sequence tank work at the task level. Lists of work items necessary to accomplish tank work have been used for some time, but time frames for execution of the task had not been put on paper. Generation and maintenance of a schedule for 1500 tasks would be impractical if done by hand. The obvious solution was a computerized Project Management system similar to those commercially available such as MS Project, Super Project, etc. Project Management software provides for the development of a data base consisting

of tasks, durations, and dates. It allows a variety of outputs such as Pert charts, Gantt charts, and resource details to be extracted. Dependencies of one task on another are accounted for.

The Outfit Planning Group decided to use a Shipyard-developed program named "Quicksched" to develop and manage the tank work data base for its first project. This program was chosen because it provided a variable format output that could be tailored to the Shipyard's needs. Data input for the first ship project was done by hand, one tank at a time. A list of repair tasks for each tank was prepared and sequenced in order of execution. In some cases, tasks were grouped together and assigned a common time frame if the sequence of execution was not important. The program software is able to identify the window for execution of a task and also the duration of the task.

In cases where sequencing was important, dependencies between tasks were entered. A sandblast sequence developed by the Outfit Planning Group was the basis for sequencing initial tasks in a tank. Previously established sequences for Special Hull Treatment application, tank testing, and other key events were used to define other task sequences and completion dates. Identification of durations for each task proved to be the most difficult part of the job. Historically, the Shipyard authorizes work in such large packages, both in manhours and in calendar time, that using cost return data to establish manhours required to complete an individual task was not possible. The Shipyard corporate knowledge about how long it takes to do work resides mostly in the heads of experienced production personnel. The Outfit Planning Group used that source to establish task durations. Figure 1 is a sample tank work sequence similar to that developed for each tank.

After completing the Quicksched data base and going through a review and revision cycle, the data base was installed on a PC computer in the dockside office of the ship's Tank Coordinator. This person is the data base custodian. At this point, the Tank Coordinator gained the following advantages:

- Lists of tasks could be easily maintained and grouped by tank or by trade.
 Windows for accomplishment
- Windows for accomplishment of tasks could be easily identified.
- 3. The ramifications of change

1 BALLAST 1 OPEN MORK PERMIT S/11 & C/330 B/17/87 B/17/87 OOD1 SUBMITTED PRICE TO SHIP ARRIVAL	3 550
1 BALLAST 1 OPEN WORK PERMIT S/II & C/330 B/17/87 B/17/87 GOOL SUBMITTED PRICE TO SHIP ARRIVAL	3 SEQ
1 BALLAST 1 OPEN WORK PERMIT S/II & C/330 B/17/87 B/17/87 GOOL SUBMITTED PRICE TO SHIP ARRIVAL	3 550
2 BALLAST 1 GPEN TANK S/11 G/17/87 G/17/87 G/001 S/18 G/17/87 G/17/87 G/17/87 G/18/87 G/18/8	
3 BALLAST 1 SAFETY INSPECTION S/11 & C/LOS 8/17/87 8/18/87 0001 BAS FREE & RADIATION SURVEY 8	. 1
V 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	2
	3
4 BALLAST 1 INITIAL CLEANING S/72 CLEANERS 8/18/87 8/19/87 (0001 B)	41
5 BALLAST 1 INITIAL INSPECTION COGNITANT SHOPS 87/19/87 8/28/87 0001 SUBMIT INSPECTION REPORT TO S/11 ETS 2002	. 5
6 BALLAST 1 PERMYE ELECTRICAL ITEMS 5/51 8/20/87 8/25/87 0002 TANK LEVEL INDICATOR & CAPLES E-3	. 6
7 BALLAST 1 PERGYE RECHAMICAL ITERS S/38 8/21/87 8/27/87 0002 BLOW VALVES 4 PERT VALVES 5 PER 5 PE	
8 BALLAST 1 REROVE PIPING 1TERS \$1758 8724/87 8229/87 0002 INTERFERENCES EXECUTED 1	8
9 BALLAST 1 RERGIVE STRUCTURAL ITERS S/11 & 5/26 8/20/87 9/1/87 COO2 1 TEMPORARY ACCESSES C. DEC. 13.	9
10 BRILLAST 1 REMOVE LEAD BALLAST S/11 18/26/87 9/1/87 0002 HEALTH HAZARD (COORD WITH CSMA) ESS-39	10
II BRILLAST I SURVEILLANCE S/II & C/135 9/1/87 9/24/87 0003 ULTRASONIC TEST OF STRUCT, MELOS	. [11]
12 BALLAST 1 INSTALL SANDELAST PROTECTION COGNIZANT SHOPS 9/1/87 9/3/87 0003	. 12
13 EBILAST 1 SANDRLAST 15/71 BLASTERS 9/3/87 9/10/87 0003 E3-3223	13
14 BALLAST 1 SURVEY INSPECTION 107250.4 % 5/11 9/10/87 9/11/87 0003 PREPARE BOCUMENT TO SHOW REPAIRS 8	14
15 BALLAST 1 PAINT 5/71 PAINTERS 9/11/87 9/18/87 6003 ALL COATS 1 1 1 1 1 1 1 1 1	15
16 BALLAST 1 SURVEY FEPAIRS S/11 & S/26 9/18/87 10/8/87 0003 WELD & SRIND DETERIORATION 1 W 1	16
17 BALLAST 1 REPAIR RECHRAICAL ITEKS S/38 9/22/87 10/8/87 0003 VENT VALVE SEAT & LINKAGES	17
18 - BALLAST 1 REPAIR PIPING ITEMS S756 9/28/87 10/13/87 0003 PER INITIAL INSPECTION FINDINGS	19
19 BALLAST 1 RESIDRE STRUCTURE S7/11 & S/28 10/8/87 10/26/87 0004 ACCESSES AND INTERFERENCES	19
20 IBALLAST 1 RESTURE PIPING SYSTEMS \$755 10713787 10722787 0004 1	20
21 BALLAST 1 RESTURE MECHANICAL SYSTEMS 10/14/87 10/22/87 0004	21
22 BALLAST 1 RESTORE ELECTRICAL SYSTEMS 9/51 10/16/87 10/28/87 0004 REPLACE INTERFERENCE REMOVALS	22
23 BALLAST 1 FLUSH PIPING S/35 TESTERS 1/0/22/87 10/22/87 10/22/87 10/29/87	23
24 BALLAST 1 TEST PIPING SYSTEMS 5/35 TESTERS 10/27/87 11/10/87 0005 STRENGTH & TIGHTNESS 10/27/87 11/10/87	24
25 IBALLAST 1 : TEST ELECTRICAL SYSTEMS 5/51 & 5/67 11/2/87 11/10/87 00005	25
26 BALLAST 1 TEST MEDICANICAL SYSTEMS 9/38 11/4/87 11/10/87 9005 STREMSTH 4 TIGHTMESS	26
27 BALLAST 1 TRSTALL LEAD BALLAST S/11 & S/72 10/26/87 11/10/87 0005 NERLTH NAZARD (COORD WITH OSNA)	27
23 BALLAST 1 TEST STRUCTURAL TIGHTNESS S/11 TESTERS 11/9/87 11/11/87 0005 22	28
27 BRILAST 1 TOUCH-UP PAINT 5/71 PAINTERS 11/10/87 11/12/87 0005	
30 BALLAST 1 FINAL MOISE SURVEY C/260 11/12/87 11/12/87 (0006 VIBRATION AND SOUND ISOLATION	30 31
31 (BALLAST 1 FIRAL MAYSEA INSPECTION (C/191 11/12/87 11/12/87 0006	
32 BALLAST 1 FINAL CLEAN 5/72 CLEAMERS 11/12/87 11/13/87 0008	D 32
33 PALLAST 1 FEMAL RECORDS CHECK C/136 & C/355 11/12/87 11/13/87 0006	E 34
34 BALLAST 1 CERTIFY WORK COMPLETE COGNIZANT SMOPS 11/13/87 0006	E 34
35 (BALLAST 1 FIRMA, SNIPSTORCE INSPECTION S/11 & SNIP 11/13/87 11/13/87 0006 ACCEPTANCE DOCUMENTATION REG'D	E 35
36 BALLAST 1 CLOSE TANK S/11 11/13/87 0007	B 36
37 (BALLAST 1 FINAL SYSTEM TESTS (COMIZANT SHOPS 11/13/87 12/4/87 0007 OPERATIONAL TESTING	37
39 (BRILAST 1 CLOSE WORK PERMIT (\$7/11 & C/330 11/13/87 (0007)	28
	AGE 1

SAMPLE TANK REPORT FIGURE 1.

- were much easier to identify. The status of work was
- easily identified. Status reports could be easily generated to suit management.
- Critical path evolutions were highlighted by the software.
- Corporate knowledge of "as accomplished" work sequences and durations was easier to retain.
- Priorities for work permits to open tanks were easier to identify and provide for Ship's Force action.
- Trade interference and competition for space were reduced.

At the date of this writing, the reaction of the top level Production management is to direct that tank repair work sequences, known as tank reports, be developed for all submarines in the Shipyard. Some of these ship overhauls were already in danger of missing schedule dates because of tank work. The tank managers for these ships adopted the tank report as a tool to minimize schedule impact. From a manager's point of view, the tank report repre-

sents a detailed plan of action to achieve schedule dates. Previously, the production working level plan to achieve schedule adherence was not all that visible to upper management. The result is a rapidly expanding program to provide project management data bases for all Shipyard tank work and all other work leading to the undocking of ships.

This Shipyard's efforts to implement project management on a large scale will impose some additional problems. The Outfit Planning Group started on a limited scale using desk top computer hardware. The purpose was to provide a tool for waterfront managers to do their jobs more effectively. Those who were involved were computer literate. The success of a computerized task management system requires dedicated personnel to provide continual attention to the data base so that current information is always available. The software must be suitable to mainframe computer systems that are likely to be in place to manage a Shipyard-wide management data base. Being restricted to PC based systems will limit the ultimate utility of the project.

Procedures and software must be made

user friendly so that special skills are not required for users to be successful. The software system used must be capable of handling large data bases, must have flexibility in output format, and must be able to communicate with other related software systems for spread sheets, data base management, and graphics production.

Finally, there exists a potential that those who monitor production will use the system to tell them if production is on track or not. If this happens on a wide scale, then the data base will come to reflect what upper management wants to hear while waterfront managers use old style methods to solve problems before upper management finds out there is a problem. This tool should be used to support tank coordinators. Management should develop its own indicators of performance that are not controlled by the people doing the work (4).

Tank Repair Unit Work Procedures

A second major area of concern to the Outfit Planning Group was the lack of specific instructions for accomplishing tank repair work. The Tank Coordinators felt that a more structured approach would cause a more uniform response on the part of all production trades and thus make the job of managing tank work easier. Initial inspection of tank systems and equipment was thought to be a good place to begin because the Shipyard has historically had problems in this area. The total extent of the repair package for a boat is not known until these inspections are done. Obviously that cannot happen until sometime after docking. The best that can be achieved is to identify the repairs as early in the overhaul as possible. This is necessary both to identify costs and to integrate the repair work into other overhaul activities. The Tank Coordinator is primarily responsible for this but must rely on other trades to inspect their systems in the tanks and report required repairs. Guidelines for these inspections either do not exist or are contained in a variety of Shipyard instructions. Consequently the effectiveness of the inspections is not consistent and required repairs are sometimes not identified until late in the overhaul.

To deal with this situation, the Outfit Planning Group has initiated the development of Unit Work Procedures, as was done by previous Outfit Planning Groups for shipalts (5). These work procedures identify what must be inspected, what acceptance

criteria apply, and specify a reporting procedure to be followed. The procedures are formatted so that each trade's inspections are grouped together. All inspections that can be done at that time during the overhaul are listed to insure that the necessity to reenter the tank will be reduced. In cases where location of the items to be inspected is not clear, graphics are provided to define locations. Figures 2 through 4 are excerpts from a prototype unit work procedure. The intention is to insure that all required inspections are accomplished and repairs are identified as early as possible during the overhaul.

Having the procedure defined in writing at the task level helps accomplish this because it defines the work that must be done in a relatively small package that makes it easy for production workers to sequence, manage, and report completion of tasks. When the work is completed, expenditures can be collected and reported back to Planning and Estimating to establish corporate history of costs at the task level. This information will provide a basis for better estimates for future work and will help to establish control limits for monitoring work in the future. A side benefit of using unit work procedures to specify initial inspection is that identification of required repairs is much easier in case the Shipyard and the Ship's Force disagree on what must be repaired.

Tank Structural Repairs

A related but separate project being pursued by the Tank Outfit Planning Group involves the development of improved ways for Design to communicate tank structural repairs to the shop based on Design's visual survey. Figures 5 and 6 show examples of tank structural deterioration. Narrative descriptions of the repairs have been used in the past. This method has been satisfactory but leaves much room for interpretation on the part of the Production worker and is time consuming for Design to produce. The intent is to reduce the preparation time and clarify the instruction by using a graphical approach to specify repairs. The key to this idea is to be able to rapidly generate graphics of tank structure as needed. CAD computers are a possible solution.

At present, CAD models of the aft trim tank and depth control tank structure on an SSN 637 Class submarine have been modeled on a CAD

œ

ı	١N	J	רו	Γ,	١X	\cap		1	7	P	P	\cap	\mathbf{C}	F	\mathbf{D}	T	ī	D	F
	, 1	v			vν	u	r	ì. F	•	r-	П.	ų,	. ,	_ թ- ,		, ,	,	П	г.

SHIP/PROJECT		,	INTER	TOR AF	TRI	м та	NK [UWP N	A-EII	03	REV
SHOP	WORK CTR	MAT'L LAND!	NB DATE		ART DATE		OMP DATE	1	ZONE WA	NAGER VIN S	/11
LEAVERTON	S/II LOF	SHOP PLANNE	IA PI	6-2315			•	COMPL	ETION CEP		
THIS UNI ACCOMPLISHE TO ESTABLIS IN THE TANK	T WORK FO IN THE	ROCEDUR	E SPEC	IFIES K. TH	INITI E INTI O IDEI	AL VI	SUAL F THE REPA	INSP SE I IRS	ECTION NSPEC TO SYS	NS TO TIONS STEMS	BE IS
SHOPS AFFEC		56,51671.	<i>;</i> }	:	٠,			·· .	۰۰۰ ۲۰۰۶	•••	, ', ', '
REQUIRE IN	TIAL INS							IN, T	CHĘ TA	NK AN	D .
5. TA 6. ZI	NK TOP	M FILL RAIN PPG INDICA PENETRAI PENETRAI	rion F.	ir, chā	ROING	SYST	EM PF	TANK G.),	· ·	
ATTACHED AR		AL INSPE						10PS	AFFEC	TED.	.; !
ALL SHOPS: 1.COMPLET 2.SEND CO 3.ROUTE F 4.REVIEW COORDINA	E "INITI PY TO S. ORM TO TANK REI	AL INSPE /II TANK P & E BY PORT SEC DATE INF	CTION COORDI PAR II DUENCE: O BASE	REPOR NATOR F FUNE S & DU D ON	T" FO ING F RATIO THE C	RM. OR RI NS AN	PAIR! D GIV ION F	S IS E S/ OUNI	REQUI	RED.	
PRECAUTIONS	12 - 1	• • •		•	٠.					٠.	٠, ,,
INFORM	ED BY S TION. INSURE T FOR ENTI SERVE S	TTEMPT /II TANK HAT THE RY" BEFO AFETY PF ORMING I	COORDI GAS FE PRE ENT RECAUT	NATOR REE CE TERING TONS C	THAT	THE	TANK	IS R	EADY.	FOR	•
DRAWN NOS.				Jo	ORDERS	3	•				
							•				
CERTIFICATI	LOFT		PLANNING		SHOP			WAT	RFRONT		
COPIES					\Box	工		П		107	
ROUTING	SHOOL PLT SHOOL	FOR HOMIL LARS	7 FEET 0.4.	<u> </u>	23 26	31 36	\$1 56	64	2 8 8	IOTAL ISSUE	

FIGURE 2.
SAMPLE UNIT WORK PROCEDURE

UNIT WOR	K PROCEDURE	(CONTINUATION SHEET)		
SHIP/PROJECT		UWF ZONE AFT TRIM	UNP NO. 113-A03	AEV

"INITIAL INSPECTION REPORT"

S/II

INSPECT STRUCTURE, PPG & ELECTRICAL PENETRATIONS, WASTER PLT, MANHOLE COVER, SEAT AND GASKET FOR THE

SAT UNS	FOLLOWING CONDITIONS:
	I.STRUCTURE MATERIAL DETERIORATION.
	2.STRUCTURE MATERIAL DEFORMATION.
-	3.WELDS FOR VISUAL DEFECTS AND COMPLETENESS.
	4.COVER GASKET FOR CUTS.TEARS, HARDENING, AGE CRACKS, WORN AREAS, PERMAMENT SET, PAINT, RUST, DIL, GREASE, OR OTHER DAMAGE/DETERIORATION, IPI 0187-019 ADDENDUM CI.
1	S.COVER SEATING SURFACE FOR NICKS, GOUGES.SCRATCHES OR CORROSION THAT WILL PERMIT LEAKAGE. (P) 0167-019 ADDENDUM C).
	6.STRONGBACK ASSEMBLY FOR EXCESSIVE WEAR OR CORROSION & PROPER INSTALLATION. IPI 0167-019 ADDENDUM CI.
.	7.LOCKING DEVISE IS "U" TYPE, SEE FIGURE C-7 (PI 0167-019 ADDENDUM C).
∵ -	8.HINGE ASSEMBLY FOR WEAR & CORROSION. IPJ 0167-019 ADDENDUM C1.
·	9.MANHOLE INSTALLED PER FIG IPI 0167-019 ADDENDUM CI.
_	, IO.TLI CABLE STUD RUNS FOR DAMAGED STUDS.
_	II.TL1 FONS FOR DAMAGE.

NOTE: I.MANHOLE INSPECTION RESULTS SHALL BE REPORTED TO C/231 ON FORM 4730/296.
2.PERFORM ZINC SURVEY OF SECT.III.I OF SSN669-633-DM513444 IN CONJUNCTION WITH ABOVE INSPECTIONS.

FIGURE 3. SAMPLE UNIT WORK PROCEDURE

UNIT WORK PROCEDURE (CONTINUATION SHEET)

SHIPPPROJECT | UNP ZONE AFT TRIM | UNP NO. | 113-A03 | REV |




FIGURE 4. SAMPLE UNIT WORK PROCEDURE



FIGURE .5.

BALLAST TANK LEAD POCKET HULL PLATING CORROSION
ELEVATION VIEW - LKG INBD



FIGURE 6. DIESEL EXHAUST ENCLOSURE - STRUCTURAL DETERIORATION

 \cdot system and are being used to provide the graphics for specifying repairs. Use of CAD generated graphics to prepare repair instructions is resulting in an estimated document preparation time savings of about 30 to 40 percent. Time saved in locating and laying out the repair work on board ship is estimated to be about 25 percent. Cost of the CAD modeling is about 5 to 10 mandays per tank. Clearly, this method is a benefit to tank work, but is costly to implement. The positive returns on the CAD investment come from developing all potential uses for the models, such as the preparation of quality control forms, and reuse of the models on all future ships of the same class. This return can be expedited by modeling

only tanks which have a high incidence of repairs. Certainly, other Ship-yards can utilize the tank models for similar purposes.

CONCLUSION

To date the Shipyard has used Outfit Planning to prepare for repair work in the areas of Special Hull Treatment and Main Sea Water Bay as well as tank repairs. A large group of Shipyard workers has been involved at one time or another. The general consensus of these people is that their participation in Outfit Planning has had a positive effect on productivity. The Production workers are encouraged by their opportunity to participate in planning for work they

will execute. The feeling is that getting the right personnel involved in a group-oriented planning activity is much better than the normal procedure which separates Planning and Production functions.

The Shipyard is now enjoying some of the benefits of Outfit Planning in the repair portion of its work. Among these benefits are:

- Breakdown of communication barriers between Planning and Production and also between system-oriented Production Trades.
- Identification of work sequences in advance of ships arrival.
- Introduction of smarter work methods.
- Reduction of reference material at the Production working level.

These benefits contribute to the Outfit Planning Group's short term goal of increasing tank repair efficiencies so that schedule is not impacted. Much of the early emphasis was on getting work done on time in lieu of saving money.

Breaking the benefits into dollars saved is a difficult task under the current fund management system and is premature at this time. The Shipyard's Industrial Engineering organization has undertaken studies to identify cost savings for some Outfit Planning efforts (6). A similar study will be necessary to identify and document savings from Tank Repair Outfit Planning. The authors feel that if such a study were done in the near future that a 10 to 20 percent savings in manhours would be identified in addition to a significant improvement in control of tank work.

ACKNOWLEDGMENTS

The authors wish to express appreciation to those who had the vision to initiate and support the effort described in this paper:

ADM. Robert E. Traister Mr. Tom Rosebraugh Mr. Mahlon Vixson

Thanks also to the individuals whose assistance was instrumental in the preparation of this paper:

Mr. Lou Chirillo Mr. Shel Kjerulf Mrs. June Loveless Mr. Mike Leverton

REFERENCES

- 1. Dennis Moen, "Application of Zone Logic and Outfit Planning Concepts to Overhaul, Modernization and Repair of U.S. Navy Ships,"

 Journal of Ship Production,

 November, 1985.
- "Shipyard Organization and Management Development," National Shipbuilding Research Program Publication, October, 1985.
- "Product Work Breakdown Structure," National Shipbuilding Research Program Publication, revised December, 1982.
- 4. W. Edwards Deming, "On Some Statistical Aids Towards Economic Production," <u>Interfaces</u>, August, 1975.
- Shel Kjerulf, "Unit Work Guide for Zone Outfitting in Repair and Overhaul," <u>Journal of Ship</u> <u>Production</u>, May, 1987.
- 6. Catherine Murphy, "Increasing Efficiency Through Outfit Planning," NSRP Ship Production Symposium, August, 1987.

Additional copies of this report can be obtained from the National Shipbuilding Research and Documentation Center:

http://www.nsnet.com/docctr/

Documentation Center
The University of Michigan
Transportation Research Institute
Marine Systems Division
2901 Baxter Road
Ann Arbor, MI 48109-2150

Phone: 734-763-2465 Fax: 734-763-4862

E-mail: Doc.Center@umich.edu